



TECHNICAL INFORMATION

Date: 04.03.2022
TI: 0123
Machine type/s: HG SiVend 15
TT

HG SiVend 15 TT Software M15Ns110

The latest HG SiVend 15 TT Software M15Ns110 offers new functions and optimises previous features. Please take note of a few highlights.

Espresso brewer

The waiting time before opening the brewing chamber has been extended or introduced.

There have also been improvements to the procedure for dealing with any overflow in the brewing chamber. Instead of switching off the machine, another attempt is made to prepare the selected hot beverage. If this second attempt is successful, the system will simply create an entry in the journal. The entry can be accessed in service menu 4L.

The machine is switched off if the second attempt also fails. The following message is shown when opening the door:

```
Malfunction C#001  
Coffee dosing  
check selection:  
3
```

The recipe must be checked or the grinder recalibrated in this case. Please refer to the operating instructions for more details.

Sielector

The Sielector connection has been improved.

Download

The latest software can be found on our homepage in the [Download Centre](#).

Vending machine	Machine control	Current software	Installed ex works for serial number:
HG SiVend 15 TT	M32	M15Ns110.pat	90538850

Sielaff GmbH & Co. KG Automatenbau Herrieden