



TECHNICAL INFORMATION

24. May 2019

TI1719

Machine type/s:

SiLine GF / SiLine SÜ

New SiLine Software

The new SiLine software offers new functions and improvements. Alongside general enhancements we would like to make you aware of several highlights.

The features listed below apply to all SiLine-machines:

Payment systems

"Empty all tubes" and "Empty tubes" functions have been improved.

Test vend

The "Test vend" function has been optimised.

Localisation

The machine display texts have been improved. In particular the English and French languages have been edited.

Administration

Management of the machine number has been optimised.

Special Functions SiLine SÜ (Spiral vending machine)

Helix Overrun

The helix overrun has been completely redesigned. When a product is dispensed the spiral makes a full turn, even if the product has been detected by light barriers. This improves the look of the machine, as the ends of all the spirals are aligned. If the light barrier has not detected a product following the spiral turning, the spiral will make a maximum of two further turns before a sold out message appears. If during this time a product is detected by the light barrier the spiral stops rotating. When the product is next selected the spiral is re-aligned with the other spirals in the machine.



TECHNICAL INFORMATION

Lift control board

Lift operation has been improved.

Any lift operating inconsistencies are now logged in the machine's journal. DebugCode 236 is displayed if the lift is not accurately positioned. DebugCode 237 is displayed for deviations in travel time.

Shelf-lookup has been improved.

The new software has already been installed on the following machines before they left the factory.

Machine	Software	Ex works from serial number
SiLine GF	0.11.2	90484159
SiLine SÜ	0.11.2	90484159

The latest corresponding software can be found on our Homepage in the Download-Center (<http://www.sielaff.de/download-center/>).

Sielaff GmbH & Co. KG